


Carvey – Preparing to Cut

Step 1: Select the right machine

- In Easel, click on the “Machine” drop-down menu.
- From the menu, select “Carvey.”
- The pink Smart Clamp area should appear in the lower corner of your design.



Step 2: Plug in the USB cord

- Plug the USB cord labeled “Connect computer here” into your laptop.




Step 3: Turn on the Carvey

- Use the power switch on the back of the Carvey to turn the machine on.
- A light should turn on inside the Carvey, and the front emergency interrupt button begin glowing blue.



Step 4: Wait for the “Carve” button to turn green

- In Easel, wait a second or two for the “Carve” button to turn from blue to green.
- If the “Carve” button does not turn green, ask a staff member for assistance. The most likely case is that the Easel drivers need updated.



Step 5: Follow the steps in the screen that pops up

- Easel will prompt you through all the remaining steps of measuring and clamping the material and confirming the bit.

